

How to measure for blinds

4 Easy Ways To Get Your Windows Covered

1 Ready Made Blinds

Available in-store.

2 Trim & Go

Get your blinds trimmed in-store.

3 Custom Express


Cut to order, quick & affordable.

4 Made to Measure


Shutters or Blinds – Endless Choices!

Outside Mount

Decide how much you would like the blind to overlap the window frame on each side, we recommend a minimum of 50mm on each side as well as the top and bottom.



Measure the width outside the window frame in 3 different locations: top (A), middle (B), and bottom (C). Use the highest width measurement.



Measure the height outside the window frame: left (D), middle (E) and right (F). Use the highest height measurement.



Free In-Home Measure & Quote
Call 080 000 2635



Instant In-Store Quote



In-Store Trim



Nationwide Installation



Delivery to Your Door



Expert Advice

Gelmar

What you need to measure:



Measuring Tape



Pencil



Step Ladder

Ensure a Clear Installation Area


Check for any obstructions such as handles, burglar guards, or other fixtures on the wall or within the window recess before installation.

Free In-Home measure & quote


Visit us in-store or
call 080 000 2635

You can install your blinds on **the inside** or **outside** of the window frame or sliding doors.

Inside Mount




Outside Mount




Inside Mount

Mounted on the inside of your window frame or sliding door.



Measure the width inside the window frame in 3 different locations: top (A), middle (B) and bottom (C). Use the smallest width measurement.



Measure the height inside the window frame: left (D), middle (E), and right (F). Use the smallest height measurement.